

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 20

Township: 7 North



Range: 1 East

Corner ID: Polk G-15

Monument Description & Remarks: Sandstone with "X", length 0.90ft, width 0.18ft, height 0.55ft. Survey Sign 5ft above ground at pt. B

References On File: Matthew Cooper survey, Boundary Survey for U.S. Department of Agriculture (2004), on file in Recorder Office cabinet S, envelope 285

RECOVERY TIE DRAWING
Field Book 39 Page No. 17




- A - Sandstone
- B - S 74° E 0.40' to Survey Sign on metal fence post
- C - S 76° W 27.57' to Sign on 17" White Oak
- D - N 18° E 20.82' to MAG nail in 17" Black Oak
- D - N 75° E 23.30' to MAG nail in 16" Red Oak



Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-11 of the Indiana Code; and the above data is given under my hand and seal this 2nd day of April, 2007.

Kevin P. Enright



Administered by the Monroe County Surveyor Review Board



Date: 4-17-2007

Index: P07

Corner: Cen ¼
S20

LAND CORNER RECORD

State of Indiana
Hoosier National Forest

P01K.G15


Township: 7N Range: 1E Section: 20 2nd P.M.

County: MONROE CO.


EXISTING SURVEYS

Original Government Survey				Original Survey Evidence Found			
Year Surveyed:		By:		Date of Search:		By:	
Original Monument:				Monument Found:			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Where Filed or Recorded:	Recorders Office			Year Searched:	1906	By: CM Bower	
Book: S.Bk.2	Page: 183	Date: 1871		Monument Found:	Not Indicated		
Monument Set:	Not Indicated						
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
W.Oak	20"	S48-1/2°W	10 ½ Lks				
W.Oak	20"	S11-1/2°W	58 ½ Lks				

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The monument is on the west edge of a north-south fence, 1.5' south of a fence running east, on a west facing slope, a large ravine begins 30' west, a small draw is 10' south.	

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.			
Center of Section 20; A 0.2'x0.9' sandstone was found 0.4' above grade with a chiseled "┘" on top. This corner was established on a 1891 Legal Survey found in Survey Book 2, page 183-184 by Alexander Spencer. This monument was found and referenced in 1990 by the Forest Service.			
Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.		
	15" Pin Oak N10°E 21.8' 14" Red Oak N65°E 24.4' 14" White Oak S85°W 28.0'		
	Corner Recordation:		Certificate Prepared:
	Filed and Recorded in County records:		Date:
	Book:		Page:
Section: 20	Geodetic Coordinates:	Lat./N.	Long./E.
	Edited By:	BTR	Date Created: 10/2004

Index: P-7	Corner: C ¼	LAND CORNER RECORD		State of Indiana Hoosier National Forest	
Twnshp: 7N	Range: 1E	Section: 20	2 nd P.M.	County	Monroe
EXISTING SURVEYS					
Original Government Survey			Original Survey Evidence Found		
Year Surveyed:	By:		Date of Search:	By:	
Original Monument:	Not Surveyed		Monument Found:		
Species	Diameter	Bearing	Distance	Species	Diameter Bearing Distance
Subsequent Corner Restoration			Evidence of Subsequent Corner Restoration Found		
Where Filed or Recorded:	Monroe county Surveyors Office		Year Searched:	11/10/03	By: B. Stone
Book: 2	Page: 183/184	Date: 11/27/1871	Monument Found	1 ½" x 10" stone standing firmly 4" above ground with shallow + on top	
Monument Set:	Not Stated				
Species	Diameter	Bearing	Distance	Species	Diameter Bearing Distance
W.Oak	20"	S 48°W	10 1/3 links		Nothing
W.Oak	20"	S 11 1/2 °W	58 ½ links		Found

OTHER EVIDENCE	
Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The stone is located on a west slope at the head of a steep hollow 0.8 feet west of a green ‘T’ shaped metal fence post with 3 strands of barbwire fence running north and south. A piece of the stone has split off along the east half of the + on top. An old decayed broken off wooden post 8” in diameter and 3 feet long with old fence wire is lying 3 feet east and uphill from the stone. Old barbwire fence runs to the east in a treeline. Timber to the northwest, southwest and southeast is sapling to pole size and more open than the larger timber to northeast on National Forest Lands. Private land to the northwest and northeast appear to be a pasture.	

PERPETUATION RECORD					
Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.					
					
Corner Diagram		Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.			
		Hickory –(with attached 2” x 4” Double stemmed W.Oak (with 6 strands of B.Oak 13” board and fence) 9” & 13” barbwire 16” S 01°W N 86° E N 16° E 13.4 Ft. 11.1 Ft. 21.6 Ft.			
		Corner Recordation:		Certificate Prepared:	
		Filed and Recorded in County records:		Date:	
		Book:		Page:	
Section: 20		State Plane Coordinates		N. 1374377.364	E. 3139999.160
		Edited By:	Robert J. Stone	Date Created:	11/18/03

Index No P-7 LAND CORNER RECORD FSM 7150
T. 7N R. 1E 2nd P.Mer. County MONROE State of Indiana
Center Corner common to Sections 20 Hoosier National Forest

EXISTING SURVEYS

Original Government Survey

Year Surveyed _____ By _____
Original Monument _____
Species Dia Bearing Dist
BT's _____

Original Survey evidence Found

Date of Search _____ By _____
Monument Found _____
Orig. Species Dia Bearing Dist
BT's _____
Found _____

Subsequent Corner Restoration

Date Surveyed _____ By _____
Where Filed or recorded: _____
Book: _____ Page _____

Monument Set

BT's Species Dia Bearing Dist
Ref. _____
Obj. _____

Evidence of Subsequent Corner Restoration Found

Date of Search _____ By _____
Monument Found _____

Species Dia Bearing Dist
BT's Found _____

Subsequent Corner Restoration

Date Surveyed _____ By _____
Where Filed or recorded: _____
Book: _____ Page _____

Monument Set

BT's Species Dia Bearing Dist
Ref. _____
Obj. _____

Evidence of Subsequent Corner Restoration Found

Date of Search _____ By _____
Monument Found _____


Species Dia Bearing Dist
BT's Found _____

OTHER EVIDENCE

Describe corner location relative to nearby features and how to reach the corner location - note fences roads, timber, streams, topo changes, etc:

Stone is 2 inches north of corner fence post
stone is located between two spurs of ridge
stone is approximately 50 ft west off ridge top.


Sketch of Monument



PERPETUATION RECORD

Monument: Describe new monument set, or work done to preserve existing monument.

CORNER DIAGRAM



Accessories: Describe new Bt's and/or witness objects established or work done to preserve existing evidence
12" Hickory 13 1/2 feet south of stone

Photo Identified

Photo # _____
Strip/Series _____
Pinpricked _____
Search Hours _____

Corner Recordation

Yes _____
Certificate prepared: No _____
Filed or recorded in County _____
Records: Date: _____
Book: _____ Page: _____

Corner Record by: Carol Ball Date: 3-6-90